




Florida Department of Transportation District Six Incident Management

Incident Management Traffic Diversion Route Plans




August 15, 2018

Contents	Page #
I-95 NB before SW 8 St	3
I-95 NB at SR 836	4
I-95 SB at SR 836	5
I-95 SB beyond SR 112	6
I-95 NB before SR 112	7
I-95 NB at SR 112	9
I-95 NB at GGI	10
I-395 EB at I-95	11
I-395 WB at Alton RD	12
I-195 EB at I-95	13
I-195 EB beyond I-95	14
I-195 WB at Alton RD	16
SR 826 NB ramp from US-1	17
SR 826 SB at SR 874	18
SR 826 NB at SR 836	19
SR 826 SB at SR 836	20
SR 826 NB at I-75	21
SR 826 SB at I-75	22
SR 826 EB at GGI	23
I-75 NB at SR 826	24
I-75 SB at SR 826	25
I-75 SB at FL Turnpike	26

Legend – Codes Used per Scenarios		
Roadways	Number of Scenarios	Direction of Roadways
A = I-95	1, 2, 3, 4, 5, 6, and 7	N = Northbound
B = I-395	1 and 2	S = Southbound
C = I-195	1, 2, and 3	E = Eastbound
D = SR 826	1, 2, 3, 4, 5, 6, and 7	W = Westbound
E = I-75	1, 2, and 3	

I-95 Procedures Scenario Code: A-1N Close entrance ramps from Rickenbacker Causeway and US-1 (all secondary Location: events will be linked to the primary event with a comment provided to justify the secondary events). I-95 NB before SW 8 St Post applicable DMS; post FLATIS message and Email (RPG). Notify Central Office as well as additional proper notifications and document **Description:** all calls in General Log/SunGuide Software. Significant event is detected Request assistance from FDOT asset-maintenance for long-term MOT. on I-95 NB before SW 8 Monitor the event with CCTV and/or Road Ranger on scene. Street which results with all



lanes closed.

Close entrance ramp from US-1 to I-95 NB.



Close entrance ramp from Rickenbacker Causeway to I-95 NB.

I-95 Scenario

Code: A-2N

Location:


I-95 NB at SR 836

Description:

Significant event is detected on I-95 NB at SR 836 which results with all lanes closed. 1. Close entrance ramp from NW 8 Street and close I-95 NB mainline.

Procedures

- 2. Post applicable DMS; post FLATIS message, and Email (RPG).
- 3. Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- 4. Request assistance from asset-maintenance for long-term MOT.
- 5. Monitor the event with CCTV and/or Road Ranger on scene.




Close entrance ramp from NW 8 Street to I-95 NB.



Close I-95 NB mainline. Traffic will be diverted to SR 836 WB and/or I-395 EB.

I-95 Procedures Scenario Code: A-3S Close I-95 SB mainline. Location: Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and I-95 SB at SR 836 document all calls in General Log/SunGuide Software. Request assistance from asset-maintenance for long-term MOT. **Description:** Significant event is detected Monitor the event with CCTV and/or Road Ranger on scene. on I-95 SB at SR 836 which results with all lanes closed.



Close I-95 SB mainline. Traffic will be diverted to I-395 EB and/or SR 836 WB.

I-95 Scenario Procedures

Code: A-4S


Location:

I-95 SB beyond SR 112

Description:

Significant event is detected on I-95 SB beyond SR 112 which results with all lanes closed.

- Close I-95 SB mainline and the entrance ramps from SR 112 EB and I-195 WB to I-95 SB
- 2. Post applicable DMS; post FLATIS message, and Email (RPG).
- 3. Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- 4. Request assistance from asset-maintenance for long-term MOT.
- 5. Monitor the event with CCTV and/or Road Ranger on scene.



If all lanes on I-95 SB beyond SR 112 are closed, traffic will be diverted to SR 112 WB and/or I-195 EB.

I-95 Scenario

Code: A-5N

Location:

I-95 NB before SR 112


Description:

Significant event is detected on I-95 NB before SR 112 which results with all lanes closed.

Procedures


- 1. Close I-95 NB mainline and the following entrance ramps
 - o SR 836 EB
 - o I-395 WB
 - o NW 8 St
- 2. Post applicable DMS; post FLATIS message, and Email (RPG).
- 3. Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
 - Request assistance from asset-maintenance for long-term MOT.
- 5. Monitor the event with CCTV and/or Road Ranger on scene.





Close I-95 NB mainline; traffic will be diverted to SR 836 WB and/or I-395 EB.

Continue page 8.



Close I-95 NB mainline; traffic will be diverted to SR 836 WB and/or I-395 EB.

I-95 Scenario Procedures

Code: A-6N

Location:

I-95 NB at SR 112

Description:


Significant event is detected on I-95 NB at SR 112 which results with all lanes closed.

- 1. Close I-95 NB mainline.
- 2. Post applicable DMS; post FLATIS message, and Email (RPG).
- 3. Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- 4. Request assistance from asset-maintenance for long-term MOT.
- 5. Monitor the event with CCTV and/or Road Ranger on scene.



Close I-95 NB mainline; traffic will be diverted to SR 112 WB and/or I-195 EB.

I-95 Procedures Scenario Code: A-7N Close all lanes on I-95 NB mainline. Location: Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and I-95 NB at GGI document all calls in General Log/SunGuide Software. Request assistance from asset-maintenance for long-term MOT. **Description:** Monitor the event with CCTV and/or Road Ranger on scene. Significant event is detected on I-95 NB at GGI which results with all lanes closed.




If all lanes are closed on I-95 NB at GGI mainline, traffic will be diverted to SR 826, US-441, TPK, and/or SR 9.

I-395 **Procedures** Scenario Code: B-1E Close all lanes on I-395 EB mainline. Location: Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and I-395 EB at I-95 document all calls in General Log/SunGuide Software. Request assistance from asset-maintenance for long-term MOT. **Description:** Significant event is detected Monitor the event with CCTV and/or Road Ranger on scene. on I-395 EB at I-95 which results with all lanes closed.



If all lanes are closed on I-395 EB mainline, traffic will be diverted to I-95 NB and/or SB.

I-395 Scenario	Procedures
Code: B-2W	
Location: I-395 WB at Alton RD	 Close all lanes on I-395 WB mainline. Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
Description: Significant event is detected on I-395 WB at/beyond Alton RD which results with all lanes closed.	 Request assistance from asset-maintenance for long-term MOT. Coordinate with Miami Beach PD for assistance. Monitor the event with CCTV and/or Road Ranger on scene.



If all lanes are closed on I-395 WB at Alton RD, traffic from Alton RD NB, SB, and WB will be inaccessible. Traffic will be diverted to Alton RD NB and/or SB.

I-195 **Procedures** Scenario Code: C-1E Close all lanes on I-195 EB mainline. Location:

Description:

I-195 EB at I-95

Significant event is detected on I-195 EB at I-95 which results with all lanes closed.

- Post applicable DMS; post FLATIS message, and Email (RPG).
- Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- Request assistance from asset-maintenance for long-term MOT.
- Monitor the event with CCTV and/or Road Ranger on scene.



If all lanes are closed on I-195 EB at I-95, traffic will be diverted to I-95 NB and/or SB.

I-195 Scenario

Procedures

Code: C-2E

Location:

I-195 EB beyond I-95

Description:

Significant event is detected on I-195 EB beyond I-95 which results with all lanes closed.

- 1. Close all lanes on I-195 EB mainline.
- 2. Post applicable DMS; post FLATIS message, and Email (RPG).
- 3. Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- 4. Request assistance from asset-maintenance for long-term MOT.
- 5. Monitor the event with CCTV and/or Road Ranger on scene.






Continue page 15.



If all lanes are closed on I-195 EB beyond I-95, traffic will be diverted to I-95 NB and/or SB. Entrance ramp from Biscayne Blvd will be inaccessible.

I-195 **Procedures Scenario** Code: C-3W Close all lanes on I-195 WB mainline. Location: Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and I-195 WB at Alton RD document all calls in General Log/SunGuide Software. Request assistance from asset-maintenance for long-term MOT. Description: Significant event is detected Coordinate with Miami Beach PD for assistance. on I-195 WB at Alton RD Monitor the event with CCTV and/or Road Ranger on scene. which results with all lanes closed.




If all lanes are closed on I-195 WB at Alton RD, traffic from Alton RD NB, SB, and WB will be inaccessible. Traffic will be diverted to Alton RD NB and/or SB.

SR 826 Procedures Scenario Code: D-1N Close entrance ramp from US-1 to SR 826 NB, including SW 100th Street Location: Post applicable DMS; post FLATIS message, and Email (RPG). SR 826 NB ramp from US-1 Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software. Description: Significant event is detected Request assistance from asset-maintenance for long-term MOT. on SR 826 NB before SW Monitor the event with CCTV and/or Road Ranger on scene. 88th Street which results with all lanes closed.



If all lanes are closed on SR 826 NB before SW 88th Street, entrance ramp from US-1 NB will be closed and traffic will be diverted to US-1 NB.

SR 826 Procedures Scenario Code: D-2S Close all lanes on SR 826 SB at SR 874. Location: Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and SR 826 SB at SR 874 document all calls in General Log/SunGuide Software. Request assistance from asset-maintenance for long-term MOT. Description: Significant event is detected Monitor the event with CCTV and/or Road Ranger on scene. on SR 826 SB at SR 874 which results with all lanes closed.




If all lanes are closed on SR 826 SB at SR 874, traffic will be diverted to SR 874 SB.

SR 826 Procedures Scenario Code: D-3N Close all lanes on SR 826 NB at SR 836. Location: Post applicable DMS; post FLATIS message, and Email (RPG). SR 826 NB at SR 836

Description:

Significant event is detected on SR 826 NB at SR 836 which results with all lanes closed.

- Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- Request assistance from asset-maintenance for long-term MOT.
- Monitor the event with CCTV and/or Road Ranger on scene.



If all lanes are closed on SR 826 NB at SR 836, traffic will be diverted to SR 836 EB and/or WB.

Note: traffic entering from West Flagler Street may be able to access SR 826 NB.

SR 826

Scenario

Location:

Code: D-4S


SR 826 SB at SR 836

Description:

Significant event is detected on SR 826 SB at SR 836 which results with all lanes closed.

Procedures

- Close all lanes on SR 826 SB at SR 836.
- Post applicable DMS; post FLATIS message, and Email (RPG).
- Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- Request assistance from asset-maintenance for long-term MOT.
- Monitor the event with CCTV and/or Road Ranger on scene.



If all lanes are closed on SR 826 SB at SR 836, traffic will be diverted to SR 836 EB and/or WB.

SR 826 Scenario Procedures

Code: D-5N


Location:

SR 826 NB at I-75

Description:

Significant event is detected on SR 826 NB at I-75 which results with all lanes closed.

- 1. Close all lanes on SR 826 NB at I-75.
- 2. Post applicable DMS; post FLATIS message, and Email (RPG).
- 3. Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- 4. Request assistance from asset-maintenance for long-term MOT.
- 5. Monitor the event with CCTV and/or Road Ranger on scene.



If all lanes are closed on SR 826 NB at I-75, traffic will be diverted to I-75.

SR 826

Scenario

Code: D-6S

Location:


SR 826 SB at I-75

Description:

Significant event is detected on SR 826 SB at I-75 which results with all lanes closed.


Procedures

- 1. Close all lanes on SR 826 SB at I-75.
- 2. Post applicable DMS; post FLATIS message, and Email (RPG).
- 3. Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software.
- 4. Request assistance from asset-maintenance for long-term MOT.
- 5. Monitor the event with CCTV and/or Road Ranger on scene.




If all lanes are closed on SR 826 SB at I-75, traffic will be diverted to I-75.

SR 826 Procedures Scenario Code: D-7E 1. Close all lanes on SR 826 EB at GGI. Location: Traffic can be diverted to I-95, SR-9, US-441, and TPK. Post applicable DMS; post FLATIS message, and Email (RPG). SR 826 EB at GGI Notify Central Office as well as additional proper notifications and document all calls in General Log/SunGuide Software. Description: Significant event is detected Request assistance from asset-maintenance for long-term MOT. on SR 826 EB at GGI which Monitor the event with CCTV and/or Road Ranger on scene. results with all lanes closed.



If all lanes are closed on SR 826 EB at GGI, traffic will be diverted to I-95, SR 9, US-441, and/or TPK.

I-75 Procedures Scenario Code: E-1N Close all lanes on I-75 NB at SR 826. Location: Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and I-75 NB at SR 826 document all calls in General Log/SunGuide Software. Request assistance from asset-maintenance for long-term MOT. Direction: Monitor the event with CCTV and/or Road Ranger on scene. Significant event is detected on I-75 NB at SR 826 which results with all lanes closed.




If all lanes are closed on I-75 NB at SR 826, traffic will be diverted to SR 826 NB and/or SB.

I-75 Procedures Scenario Code: E-2S Close all lanes on I-75 SB at SR 826. Location: Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and I-75 SB at SR 826 document all calls in General Log/SunGuide Software. Request assistance from asset-maintenance for long-term MOT. **Description:** 5. Monitor the event with CCTV and/or Road Ranger on scene. Significant event is detected on I-75 SB at SR 826 which results with all lanes closed.



If all lanes are closed on I-75 SB at SR 826, traffic will be diverted to SR 826 NB and/or SB.

I-75 Procedures Scenario Code: E-3S Close all lanes on I-75 SB at FL Turnpike. Location: Post applicable DMS; post FLATIS message, and Email (RPG). Notify Central Office as well as additional proper notifications and I-75 SB at FL Turnpike document all calls in General Log/SunGuide Software. Request assistance from asset-maintenance for long-term MOT. Description: Monitor the event with CCTV and/or Road Ranger on scene. Significant event is detected on I-75 SB at Turnpike which results with all lanes closed.



If all lanes are closed on I-75 SB at Florida's Turnpike, traffic will be diverted to Florida's Turnpike SB.