


TRANSPORTATION SYSTEMS MANAGEMENT & OPERATIONS (TSM&O)

1001 N.W. 111 Avenue, Miami, Florida 33172 Phone: 305.470.5757 Fax: 305.470.5832 **SunGuide.info** 

# **DMS Usage Report – June 2024**



### Average DMS Monthly Availability (%)

# 98.24

## **Top Two Safety Messages of the Month**

DON'T DRIVE DROWSY

ARRIVE ALIVE

Total Publications: 1.928

Total Publications: 1,925

DRIVING ALERT
CAN KEEP
YOU SAFE

**1** | P a g e File Code: 502.4.3.4 Publication Date: July 11, 2024



TRANSPORTATION SYSTEMS MANAGEMENT & OPERATIONS (TSM&O)

1001 N.W. 111 Avenue, Miami, Florida 33172 Phone: 305.470.5757 Fax: 305.470.5832 **SunGuide.info** 

### DMS Usage by Roadway (Limited Access Facilities)

Roadway	ID	Location	# of Activations	# of Messages	Duration (hr:mm:ss)	Availability
I-95 MAINLINE	1	I-95 NB beyond NW 103 St	216	670	748:54:06	100.00%
	22	I-95 NB south of NW 62 St	165	436	443:44:19	100.00%
	75**	I-95 NB before SR 112	223	574	237:36:41	N/A
	77*	I-95 NB beyond SW 8 St	254	722	559:50:33	N/A
	2	I-95 SB north of Ives Dairy Rd	294	785	430:41:11	100.00%
	3	I-95 SB north of Miami Gardens Dr	238	704	390:21:08	97.35%
	095NB013.5LL	I-95 NB north of NW 173 St	108	406	442:10:21	99.89%
	20	I-95 SB south of NW 119 St	134	426	352:46:16	100.00%
	21	I-95 SB south of NW 62 St	221	721	691:24:10	100.00%
	74**	I-95 SB beyond SR 112	226	699	814:50:48	N/A
	76*	I-95 SB before Rickenbacker Cswy	28	73	298:23:46	N/A
		I-95 MAINLINE SUBTOTAL	2107	6216	5410:43:19	99.61%
	95XNB40	95X NB at NW 62 St	121	331	290:00:14	100.00%
	95XNB45	95X NB at NW 125 St	150	460	490:10:36	99.56%
	95XSB45	95X SB at NW 62 St	209	679	685:51:42	100.00%
95 EXPRESS	95XSB50	95X SB at NW 125 St	117	268	277:48:50	100.00%
	095SB014.6-EL	95X SB at Miami Gardens Dr	230	530	390:44:36	95.50%
	095NB014.8-EL	95X NB north of Miami Gardens Dr	55	206	264:21:38	80.33%
		95 EXPRESS SUBTOTAL	882	2474	2398:57:36	95.90%
	4	SR 826 EB east of NW 67 Ave	76	152	381:57:31	100.00%
	5	SR 826 EB east of NW 37 Ave	280	882	886:37:23	100.00%
	826NB014.38	SR 826 NB beyond NW 122 St	79	214	127:06:51	100.00%
	15 <sup>†</sup>	SR 826 WB beyond NW 17 Ave	57	149	140:35:06	N/A
	17 <sup>††</sup>	SR 826 WB beyond NW 47 Ave	126	378	1134:53:01	87.45%
	19	SR 826 WB beyond NW 67 Ave	195	674	1499:39:40	100.00%
	826NB010.36	SR 826 NB before NW 58 St	106	266	493:34:16	92.20%
SR 826 &	826SB013.74	SR 826 SB before NW 103 St	172	485	1105:45:45	100.00%
PALMETTO EXPRESS	826SB10.99	SR 826 SB before NW 58 St	74	162	57:16:33	100.00%
27.77.233	826NB008.48	SR 826 NB at NW 25 St	113	313	514:34:32	
		SR 826 SB at NW 66 St	57	107	117:39:37	100.00%
	826ELSB010.84					99.98%
	826ELNB013.55	SR 826 NB at NW 108 St	25	37	99:32:10	99.72%
	826NB001.3-LL	SR 826 NB before SW 72 St	75	187	133:43:00	100.00%
	826NB004.8-LL	SR 826 NB at SW 24 St	226	546	989:36:24	100.00%
	826SB008.8-LL	SR 826 SB at NW 36 St	186	428	649:57:14	100.00%
		SR 826 SUBTOTAL	1847	4980	8332:29:03	98.53%
	075NB002.68	I-75 NB before Miami Gardens Dr	24	53	100:52:19	100.00%
	075NB001.32	I-75 AT NW 89 Ave	26	58	101:13:08	98.58%
I-75 & 75 EXPRESS	075SB001.29	I-75 SB ramp from NW 138 St	190	611	1131:59:17	100.00%
	075SB000.4-EL	I-75 SB before HEFT	43	105	479:02:02	99.44%
	075SB004.1-LL	I-75 SB South of Miami Gardens Dr	169	542	1409:24:11	98.65%
		I-75 SUBTOTAL	452	1369	3222:30:57	99.33%
I-195	57	I-195 EB before North Miami Ave	32	58	125:09:58	99.96%
MAINLINE	105*	I-195 WB before Alton Rd	30	86	56:15:43	N/A
		I-195 MAINLINE SUBTOTAL	62	144	181:25:41	99.96%
1 205	886WB	Port Blvd WB before US 1	208	528	715:10:33	100.00%
I-395	104**	I-395 WB at Watson Island	294	804	675:38:39	N/A
		I-395 SUBTOTAL	502	1332	1390:49:12	100.00%
		LIMITED ACCESS FACILITIES SUBTOTAL	5852	16515	20936:55:48	98.49%

2 | Page **Publication Date: July 11, 2024** File Code: 502.4.3.4



TRANSPORTATION SYSTEMS MANAGEMENT & OPERATIONS (TSM&O)

1001 N.W. 111 Avenue, Miami, Florida 33172 Phone: 305.470.5757 Fax: 305.470.5832 **SunGuide.info** 

### DMS Usage by Roadway (Arterials)

Roadway	ID	Location	# of Activations	# of Messages	Duration (hr:mm:ss)	Availability
	109	Ives Dairy Rd EB before I-95	170	489	292:17:57	98.60%
	113	Ives Dairy Rd WB before I-95	165	477	316:17:34	99.78%
	110	Miami Gardens Dr EB before I-95	187	615	313:00:14	98.74%
	111	Miami Gardens Dr WB before I-95	195	654	294:54:02	98.98%
I-95 ARTERIAL	112	NW 103 St EB before I-95	237	737	547:09:13	95.90%
	106	NW 79 St EB before I-95	300	957	715:49:11	100.00%
	107 <sup>††</sup>	NW 54 St EB before I-95	267	857	698:44:45	88.02%
	108	SW 8 St EB before I-95	131	421	295:10:11	100.00%
'		I-95 ARTERIAL SUBTOTAL	1758	6102	6783:26:52	98.09%
	6 <sup>†</sup>	SR 826 WB west of NE 2 Ave	278	939	710:30:38	N/A
	7	Turnpike SB to Golden Glades	226	714	561:20:33	100.00%
GOLDEN GLADES INTERCHANGE	$9^{t}$	US 441 NB at Tri-Rail	78	238	260:09:33	N/A
INTERCHANGE	10 <sup>†</sup>	SR 9 NB before Park & Ride	95	286	326:55:20	N/A
	8	US 441 SB at NW 179 St	190	588	281:23:32	99.96%
'	GOLD	EN GLADES INTERCHANGE SUBTOTAL	867	2765	2140:19:36	99.98%
	SW24EB	SW 24 St EB before SR 826	136	336	474:46:03	95.47%
	SW24WB	SW 24 St WB before SR 826	143	349	494:46:34	100.00%
	SW40EB	SW 40 St EB before SR 826	105	274	156:12:06	100.00%
	SW40WB	SW 40 St WB before SR 826	101	270	156:06:49	100.00%
	SW56EB	SW 56 St EB before SR 826	89	238	140:23:08	100.00%
	SW56WB	SW 56 St WB before SR 826	84	229	130:08:03	91.80%
	SW72EB	SW 72 St EB before SR 826	89	238	140:47:17	100.00%
	SW72WB <sup>‡</sup>	SW 72 St WB before SR 826	10	34	2:22:27	N/A
SR 826	SR968EB*	W Flagler St EB before SR 826	133	358	500:24:52	N/A
ARTERIAL	SR968WB*	W Flagler St WB before SR 826	133	356	500:24:40	N/A
	NW25EB*	NW 25 St EB before SR 826	19	38	43:13:32	N/A
	NW25WB*	NW 25 St WB before SR 826	19	36	43:12:43	N/A
	NW36EB*	NW 36 St EB before SR 826	19	41	42:41:27	N/A
	NW36WB	NW 36 St WB before SR 826	149	367	188:07:58	100.00%
	SW8EB	SW 8 St EB before SR 826	146	380	507:48:00	100.00%
	SW8WB	SW 8 St WB before SR 826	146	380	507:48:00	100.00%
	SW88EB*	Kendall Dr EB before SR 826	8	10	1:20:14	N/A
	SW88WB*	Kendall Dr WB before SR 826	8	10	1:20:16	N/A
	ADMS-103ST-EB	NW 103 St EB before SR 826	171	456	533:39:44	99.16%
	ADMS-103ST-WB <sup>††</sup>	NW 103 St WB before SR 826	157	425	530:51:49	89.65%
	ADMS-122ST-EB	NW 122 St EB before SR 826	215	689	1114:23:58	100.00%
	ADMS-122ST-WB	NW 122 St WB before SR 826	208	667	1091:47:01	99.07%
	ADMS-154ST-EB	NW 154 St EB before SR 826	179	582	1104:10:32	100.00%
	ADMS-154ST-WB	NW 154 St WB before SR 826	182	589	1109:55:48	100.00%
	ADMS-58ST-WB	NW 58 St WB before SR 826	160	370	539:26:05	99.96%
	ADMS-74ST-EB	NW 74 St EB before SR 826	147	377	719:34:46	100.00%
	ADMS-74ST-WB	NW 74 St WB before SR 826	170	417	822:06:58	100.00%
	ADMS-US27-EB	US 27 EB before SR 826	171	476	914:11:09	100.00%
	ADMS-US27-WB	US 27 WB before SR 826	180	502	924:15:30	100.00%
		SR 826 ARTERIAL SUBTOTAL	3477	9494	13436:17:29	98.81%

3 | P a g e File Code: 502.4.3.4 Publication Date: July 11, 2024



TRANSPORTATION SYSTEMS MANAGEMENT & OPERATIONS (TSM&O)

1001 N.W. 111 Avenue, Miami, Florida 33172

Phone: 305.470.5757 Fax: 305.470.5832 SunGuide.info

Roadway	ID	Location	# of Activations	# of Messages	Duration (hr:mm:ss)	Availability
I-195 ARTERIAL	38	Alton Rd SB before I-195	104	284	224:21:52	100.00%
	39 <sup>‡‡</sup>	Arthur Godfrey WB before I-195	72	230	111:09:15	82.02%
	40 <sup>‡‡</sup>	Alton Rd NB before I-195	73	235	116:48:58	81.33%
		I-195 ARTERIAL SUBTOTAL	249	749	452:20:05	87.78%
I-75 ARTERIAL	ADMS-W80ST-NB	Hialeah Grdns Blvd NB before I-75	181	609	1097:57:34	100.00%
	ADMS-NW138ST-EB	NW 138th St EB before I-75	179	609	1097:07:13	100.00%
		I-75 ARTERIAL SUBTOTAL	360	1218	2195:04:47	100.00%
	23	US 1 NB beyond SW 17 Ave	205	604	602:02:56	100.00%
4 50014 4 05	45	US 1 SB before SW 80 St	33	71	138:49:04	100.00%
US 1 FROM I-95 TO BEGINNING	47	US 1 SB at Florida's Turnpike	22	34	111:04:39	99.69%
OF HEFT	46	US 1 NB before Killian Dr	56	152	140:35:02	95.89%
	48	US 1 NB at Florida's Turnpike	26	38	112:19:30	100.00%
US 1 FROM I-95 TO BEGINNING OF HEFT SUBTOTAL			394	964	1215:16:48	99.37%
US 27 OKEECHOBEE RD	US27KROME-SB	US 27 SB at Krome Ave	0	0	0:00:00	100.00%
	US27NW186ST-NB	US 27 NB at NW 186 St	0	0	0:00:00	100.00%
·		US 27 TO OKEECHOBEE RD SUBTOTAL	0	0	0:00:00	100.00%
	62	US 1 NB at Mile Marker 126	5	11	11:37:13	95.41%
	64	US 1 NB at Mile Marker 106	20	56	47:47:17	100.00%
	66	US 1 NB at Mile Marker 91.5	42	161	232:14:09	99.96%
US 1 SOUTH OF BEGINNING OF HEFT	68	US 1 NB at Mile Marker 39.5	49	288	976:59:59	99.72%
	71	US 1 NB at Mile Marker 7.5	65	313	1047:15:29	96.96%
	61	US 1 SB at Mile Marker 126	24	144	793:36:37	92.55%
	63	US 1 SB at Mile Marker 113	12	139	743:01:42	98.87%
	65	US 1 SB at Mile Marker 106	10	135	771:36:46	100.00%
	67	US 1 SB at Mile Marker 91.5	8	123	743:30:36	99.86%
	69	US 1 SB at Mile Marker 39.5	5	15	28:07:28	99.66%
	70	US 1 SB at Mile Marker 7.5	3	5	22:35:30	99.08%
US 1 SOUTH OF BEGINNING OF HEFT SUBTOTAL			243	1,390	5418:22:46	98.37%
		ARTERIALS SUBTOTAL	7,190	21,722	28220:39:01	98.08%
	L	IMITED ACCESS FACILITIES SUBTOTAL	5,852	16,515	20936:55:48	98.49%
		GRAND TOTAL	13,042	38,237	49157:34:49	98.24%

<sup>\*</sup> DMS under ITS DMS Replacement Projects. System availability is not measured for these devices.

4 | P a g e File Code: 502.4.3.4 Publication Date: July 11, 2024

<sup>\*\*</sup> DMS under the I-395/SR 836/I-95 Design Build Contractor. System availability is not measured for these devices.

<sup>†</sup> DMS under Golden Glades Interchange Enhancement Project. System availability is not measured for these devices.

<sup>++</sup> DMS had communication issues and repairs were made. System availability is measured for these devices.

<sup>‡</sup> DMS power conduit damaged by FPL. System availability is not measured for these devices.

<sup>‡‡</sup> DMS had fiber link missing in cabinet and repairs were made. System availability is measured for these devices.