


TRANSPORTATION SYSTEMS MANAGEMENT & OPERATIONS (TSM&O)

1001 N.W. 111 Avenue, Miami, Florida 33172 Phone: 305.470.5757 Fax: 305.470.5832 **SunGuide.info**

DMS Usage Report – October 2025



Average DMS Monthly Availability (%)

97.75

Top Two Safety Messages of the Month

BE VISIBLE
NO TAILGATING

Total Publications: 2.417

Total Publications: 2,320

FENDER BENDER MOVE VEHICLES DRIVE SAFELY

1 | P a g e File Code: 502.4.3.4 Publication Date: November 10, 2025



TRANSPORTATION SYSTEMS MANAGEMENT & OPERATIONS (TSM&O)

1001 N.W. 111 Avenue, Miami, Florida 33172 Phone: 305.470.5757 Fax: 305.470.5832 **SunGuide.info**

DMS Usage by Roadway (Limited Access Facilities)

Roadway	ID	Location	# of Activations	# of Messages	Duration (hr:mm:ss)	Availability
	1	I-95 NB beyond NW 103 St	216	736	648:18:00	99.46%
	22	I-95 NB south of NW 62 St	188	548	510:00:33	100.00%
	75*	I-95 NB before SR 112	265	657	412:26:16	N/A
	77 [‡]	I-95 NB beyond SW 8 St	264	652	763:39:48	72.55%
	2	I-95 SB north of Ives Dairy Rd	284	768	709:49:41	99.87%
I-95 MAINLINE	3	I-95 SB north of Miami Gardens Dr	257	725	676:16:31	99.87%
MANUELINE	095NB013.5LL	I-95 NB north of NW 173 St	96	343	263:42:31	99.82%
	20	I-95 SB south of NW 119 St	155	434	406:03:02	100.00%
	21	I-95 SB south of NW 62 St	186	567	446:12:06	100.00%
	74*	I-95 SB beyond SR 112	206	641	1069:55:11	N/A
	76	I-95 SB before Rickenbacker Cswy	8	22	3:50:49	99.74%
·		I-95 MAINLINE SUBTOTAL	2125	6093	5910:14:28	96.81%
	95XNB40	95X NB at NW 62 St	147	444	616:29:55	99.74%
	95XNB45	95X NB at NW 125 St	190	614	705:03:09	99.76%
	95XSB45	95X SB at NW 62 St	159	533	450:14:57	99.87%
95 EXPRESS	95XSB50	95X SB at NW 125 St	116	292	156:36:45	97.80%
	095SB014.6-EL	95X SB at Miami Gardens Dr	240	584	659:09:26	99.82%
	095NB014.8-EL	95X NB north of Miami Gardens Dr	60	189	193:58:50	99.00%
		95 EXPRESS SUBTOTAL	912	2656	2781:33:02	99.33%
	4**	SR 826 EB east of NW 67 Ave	21	67	29:58:28	25.59%
	5	SR 826 EB east of NW 37 Ave	306	964	703:50:53	100.00%
	826NB014.38	SR 826 NB beyond NW 122 St	68	211	100:25:04	99.83%
	15**	SR 826 WB beyond NW 17 Ave	40	90	66:42:20	N/A
	17	SR 826 WB beyond NW 47 Ave	77	162	98:47:32	99.83%
	19	SR 826 WB beyond NW 67 Ave	133	335	119:58:29	99.89%
	826NB010.36	SR 826 NB before NW 58 St	94	272	126:16:12	100.00%
SR 826 & PALMETTO	826SB014.41	SR 826 SB north of NW 122 St	134	352	103:43:36	99.69%
EXPRESS	826SB10.99	SR 826 SB before NW 58 St	121	335	62:31:50	99.87%
	826NB008.48	SR 826 NB at NW 25 St	101	299	111:48:44	99.89%
	826ELSB010.84	SR 826 SB at NW 66 St	115	248	87:41:50	99.86%
	826ELNB013.55	SR 826 NB at NW 108 St	24	62	65:11:50	99.86%
	826NB001.3-LL	SR 826 NB before SW 72 St	68	157	73:26:03	99.79%
			194			
	826NB004.8-LL	SR 826 NB at SW 24 St	_	522	383:17:39	99.27%
	826SB008.8-LL*	SR 826 SB at NW 36 St SR 826 SUBTOTAL	169	475	355:55:22	88.11%
	075NB002.68	I-75 NB before Miami Gardens Dr	1665	4551	2489:35:52	93.68%
			22 24	64 66	67:05:41	99.82%
	075NB001.32	I-75 AT NW 89 Ave			67:07:39	99.82%
I-75 & 75 EXPRESS	075SB001.29	I-75 SB ramp from NW 138 St	113	361	120:58:36	100.00%
LAPALSS	075SB000.4-EL	I-75 SB before HEFT	48	99	74:07:09	97.87%
	075SB004.1-LL	I-75 SB South of Miami Gardens Dr	145	373	116:40:30	99.82%
		I-75 SUBTOTAL	352	963	445:59:35	99.47%
I-195	57	I-195 EB before North Miami Ave	30	53	59:22:53	100.00%
MAINLINE	105	I-195 WB before Alton Rd	211	613	458:03:28	99.96%
	0061475	I-195 MAINLINE SUBTOTAL	241	666	517:26:21	99.98%
I-395	886WB	Port Blvd WB before US 1	247	545	859:26:29	98.34%
	104*	I-395 WB at Watson Island	344	820	1042:50:31	N/A
		I-395 SUBTOTAL	591	<i>1365</i>	1902:17:00	98.34%

2 | Page File Code: 502.4.3.4 **Publication Date: November 10, 2025**



TRANSPORTATION SYSTEMS MANAGEMENT & OPERATIONS (TSM&O)

1001 N.W. 111 Avenue, Miami, Florida 33172 Phone: 305.470.5757 Fax: 305.470.5832 **SunGuide.info**

DMS Usage by Roadway (Arterials)

Roadway	ID	Location	# of Activations	# of Messages	Duration (hr:mm:ss)	Availability
	109	Ives Dairy Rd EB before I-95	168	470	367:00:57	96.89%
	113	Ives Dairy Rd WB before I-95	171	480	400:53:23	95.72%
	110 [‡]	Miami Gardens Dr EB before I-95	171	479	280:41:23	84.24%
	111	Miami Gardens Dr WB before I-95	210	624	432:29:19	99.41%
I-95 ARTERIAL	112	NW 103 St EB before I-95	291	905	541:58:03	97.91%
	106	NW 79 St EB before I-95	319	978	613:20:20	97.80%
	107	NW 54 St EB before I-95	335	974	581:21:34	99.87%
	108	SW 8 St EB before I-95	201	509	375:23:39	99.87%
· · · · · · · · · · · · · · · · · · ·		I-95 ARTERIAL SUBTOTAL	1866	5419	3593:08:38	96.46%
	6**	SR 826 WB west of NE 2 Ave	44	154	83:32:26	N/A
	7	Turnpike SB to Golden Glades	259	820	457:59:31	99.85%
OLDEN GLADES INTERCHANGE	9**	US 441 NB at Tri-Rail	116	453	575:33:14	N/A
INTERCHANGE	10**	SR 9 NB before Park & Ride	115	443	595:04:37	N/A
	8	US 441 SB at NW 179 St	208	662	640:56:56	99.75%
· · · · · · · · · · · · · · · · · · ·	GOLD	EN GLADES INTERCHANGE SUBTOTAL	742	2532	2353:06:44	99.80%
	SW24EB	SW 24 St EB before SR 826	136	379	116:00:52	99.95%
	SW24WB	SW 24 St WB before SR 826	136	379	116:00:50	99.91%
	SW40EB	SW 40 St EB before SR 826	133	335	150:14:17	99.91%
	SW40WB	SW 40 St WB before SR 826	131	333	150:25:57	99.91%
	SW56EB	SW 56 St EB before SR 826	97	249	87:33:23	99.76%
	SW56WB	SW 56 St WB before SR 826	97	249	87:33:15	99.83%
	SW72EB	SW 72 St EB before SR 826	86	211	85:42:49	99.83%
	SW72WB	SW 72 St WB before SR 826	75	198	35:01:51	99.32%
SR 826	SR968EB	W Flagler St EB before SR 826	149	418	139:35:16	99.75%
ARTERIAL	SR968WB	W Flagler St WB before SR 826	148	424	139:59:13	99.91%
	NW25EB	NW 25 St EB before SR 826	184	496	154:02:20	99.91%
	NW25WB ^{‡‡}	NW 25 St WB before SR 826	166	445	135:31:47	86.77%
	NW36EB	NW 36 St EB before SR 826	176	508	154:17:24	95.45%
	NW36WB	NW 36 St WB before SR 826	167	469	144:05:25	91.87%
	SW8EB	SW 8 St EB before SR 826	144	414	123:03:11	99.91%
	SW8WB	SW 8 St WB before SR 826	143	413	122:42:58	99.91%
	SW88EB	Kendall Dr EB before SR 826	55	135	18:33:28	97.34%
	SW88WB	Kendall Dr WB before SR 826	56	138	18:44:01	99.93%
	ADMS-103ST-EB	NW 103 St EB before SR 826	145	437	113:40:30	99.82%
	ADMS-103ST-WB	NW 103 St WB before SR 826	144	429	114:06:35	99.82%
	ADMS-122ST-EB	NW 122 St EB before SR 826	145	419	115:38:09	99.82%
	ADMS-122ST-WB	NW 122 St WB before SR 826	146	424	116:29:11	99.78%
	ADMS-154ST-EB	NW 154 St EB before SR 826	134	398	111:02:50	99.82%
	ADMS-154ST-WB	NW 154 St WB before SR 826	132	400	111:02:31	99.79%
	ADMS-58ST-WB	NW 58 St WB before SR 826	190	535	135:09:04	99.75%
	ADMS-74ST-EB	NW 74 St EB before SR 826	150	445	69:11:24	99.82%
	ADMS-74ST-WB	NW 74 St WB before SR 826	165	481	121:26:08	99.82%
	ADMS-US27-EB***	US 27 EB before SR 826	165 173	491	122:32:30	N/A
	ADMS-US27-WB***	US 27 WB before SR 826	172	540	134:10:02	N/A

3 | Page Publication Date: November 10, 2025 File Code: 502.4.3.4



TRANSPORTATION SYSTEMS MANAGEMENT & OPERATIONS (TSM&O)

1001 N.W. 111 Avenue, Miami, Florida 33172

Phone: 305.470.5757 Fax: 305.470.5832 SunGuide.info

Roadway	ID	Location	# of Activations	# of Messages	Duration (hr:mm:ss)	Availability
I-195 ARTERIAL	38	Alton Rd SB before I-195	131	394	263:22:05	99.40%
	39	Arthur Godfrey WB before I-195	121	368	219:38:11	100.00%
ANTENIAL	40	Alton Rd NB before I-195	121	374	221:16:25	99.98%
		I-195 ARTERIAL SUBTOTAL	373	1136	704:16:41	99.79%
I-75	ADMS-W80ST-NB	Hialeah Grdns Blvd NB before I-75	115	395	107:56:38	99.87%
ARTERIAL	ADMS-NW138ST-EB	NW 138th St EB before I-75	115	388	107:54:36	99.76%
·		I-75 ARTERIAL SUBTOTAL	230	783	215:51:14	99.82%
	23	US 1 NB beyond SW 17 Ave	251	649	597:24:06	98.40%
US 1 FROM I-95	45 ^{††}	US 1 SB before SW 80 St	15	32	44:28:57	N/A
TO BEGINNING	47	US 1 SB at Florida's Turnpike	14	30	53:53:10	99.87%
OF HEFT	46	US 1 NB before Killian Dr	49	113	87:12:38	99.81%
	48	US 1 NB at Florida's Turnpike	19	35	58:02:39	99.75%
	US 1 FROM I-9	5 TO BEGINNING OF HEFT SUBTOTAL	348	859	841:01:30	99.46%
US 27	US27KROME-SB	US 27 SB at Krome Ave	10	31	10:51:58	99.20%
OKEECHOBEE RD	US27NW186ST-NB	US 27 NB at NW 186 St	0	0	0:00:00	99.37%
		US 27 TO OKEECHOBEE RD SUBTOTAL	10	31	10:51:58	99.29%
	62*	US 1 NB at Mile Marker 126	2	8	47:13:28	N/A
	64*	US 1 NB at Mile Marker 106	13	51	244:30:24	N/A
	66*	US 1 NB at Mile Marker 91.5	12	54	320:05:56	N/A
	68*	US 1 NB at Mile Marker 39.5	14	160	359:07:02	N/A
US 1 SOUTH OF	71*	US 1 NB at Mile Marker 7.5	16	112	196:45:03	N/A
BEGINNING OF	61*	US 1 SB at Mile Marker 126	19	116	263:58:43	N/A
HEFT	63*	US 1 SB at Mile Marker 113	17	339	946:30:26	N/A
	65*	US 1 SB at Mile Marker 106	9	89	175:11:20	N/A
	67 *	US 1 SB at Mile Marker 91.5	9	145	322:24:44	N/A
	69*	US 1 SB at Mile Marker 39.5	7	23	94:03:38	N/A
	70*	US 1 SB at Mile Marker 7.5	6	27	124:20:15	N/A
US 1 SOUTH OF BEGINNING OF HEFT SUBTOTAL		124	1,124	3094:10:59	N/A	
		TOTAL NUMBER OF DMS	106 [†]			
		ARTERIALS SUBTOTAL	7,660	23,076	14056:04:55	98.63%
	L	IMITED ACCESS FACILITIES SUBTOTAL	5,886	16,294	14047:06:18	96.61%
		GRAND TOTAL	13,546	39,370	28103:11:13	97.75%

- * DMS under the I-395/SR 836/I-95 Design Build Contractor. System availability is not measured for these devices.
- ** DMS under Golden Glades Interchange Enhancement Project. System availability is not measured for these devices.
- *** DMS under SR 25/US 27/Okeechobee Rd Improvement Project. System availability is not measured for these devices.
 - † DMS-826SB013.74 was removed by the SR 826/Palmetto Express Capacity Improvement Project.
- ++ DMS under Cabinet Replacement Project. System availability is not measured for these devices.
- ‡ DMS had equipment malfunctions and repairs were made. System availability is measured for these devices.
- ‡‡ DMS had communication issues and repairs were made. System availability is measured for these devices.
- DMS had power issues and repairs were made. System availability is measured for these devices.
- DMS had fiber optic issues and repairs were made. System availability is measured for these devices.
- DMS had network issues due to regional fiber optic disruption. System availability is not measured for these devices.

4 | P a g e File Code: 502.4.3.4 Publication Date: November 10, 2025